B R L ADA 154274

SPECIAL PUBLICATION BRL-SP-46

TECHNICAL LIBRARY

RACK FOR TEMPORARY STORAGE OF 105 MM HEAT AMMUNITION

Philip M. Howe

March 1985

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

US ARMY BALLISTIC RESEARCH LABORATORY ABERDEEN PROVING GROUND, MARYLAND

Destroy this report when it is no longer needed. Do not return it to the originator.

Additional copies of this report may be obtained from the National Technical Information Service, U. S. Department of Commerce, Springfield, Virginia 22161.

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

The use of trade names or manufacturers' names in this report does not constitute indorsement of any commercial product.



DEPARTMENT OF THE ARMY

UNITED STATES ARMY LABORATORY COMMAND
BALLISTIC RESEARCH LABORATORY
ABERDEEN PROVING GROUND, MARYLAND 21005-5066

REPLY TO ATTENTION OF

SLCBR-TB-E

27 May 1986

SUBJECT: Rack for Temporary Storage of 105 mm HEAT Ammunition

See Distribution

1. References:

- a. Ballistic Research Laboratory Special Publication 46 entitled Rack for Temporary Storage of 105 mm HEAT Ammunition by Philip M. Howe, March 1986.
- b. Message from USASC (PESC-PR), Fort Rucker, AL, subject as above, 251500Z November 1985 (NOTAL).
- c. Message, USASC (PESC-PR), Fort Rucker, AL, subject as above, 011745Z May 1986 (NOTAL).
- 2. In response to reference c, it is recommended that the use of the rack as described in reference a and approved for use in reference b be temporarily suspended.
- 3. Recent tests by BRL indicate that a modification to the rack and its sandbagging is required to meet the 50-foot criteria for secondary fragments.
- 4. Detailed descriptions as to what modifications are required will be forthcoming as soon as safety approvals have been granted.

ROBERT B. FREY

Acting Chief

Explosive Effects Branch

Ora R. Lymon for RF.

SUBJECT: Rack for Temporary Storage of 105 mm HEAT Ammunition

Distribution:

Administrator, Defense Technical Info Center, ATTN: DTIC-DDA, Cameron

Station, Alexandria, VA 22314

HQDA (DAMA-ART-M), Washington, DC 20310

Chairman, DOD Explosives Safety Board, ATTN: Dr. T. Zaker, COL O. Westry, Room 856-C, Hoffman Bldg 1, 2461 Eisenhower Avenue, Alexandria, VA 22331 Under Secretary of Defense for Research & Engineering, Department of Defense,

Washington, DC 20301

Assistant Secretary of Defense (MRA+L) ATTN: EO&SP, Washington, DC 20301

HQDA (DAMA-CMS-CA/Mr. Lippi), Washington, DC 20310

HQDA (DAMO-NC/COL R. D. Orton), Washington, DC 20310

HQDA (DAPE-HRS), Washington, DC 20310

HQDA-(DCSLOG/Elliot_Seard), Washington, DC 20310

Assistant Secretary of Army (I&L), Department of the Army, ATTN: Lewis D.

Walker, John Nash, Room 3E606, Pentagon, Washington, DC 20310

Commander, USA Safety Center, ATTN: PESC-Z, Fort Rucker, AL 36360

Commander, US Army Materiel Command, ATTN: AMCDRA-ST, 5001 Eisenhower Avenue, Alexandria, VA 22333-0001

Commander, US Army Materiel Command, ATTN: AMCSF, 5001 Eisenhower Avenue, Alexandria, VA 22333

Director, AMC Field Safety Activity, Charlestown, IN 47111

Commander, Armament R&D Center, US Army AMCCOM, ATTN: SMCAR-TDC, Dover, NJ 07801

Commander, Armament R&D Center, US Army AMCCOM, ATTN: SMCAR-TSS, Dover, NJ 07801

Commander, Armament R&D Center, US Army AMCCOM, ATTN: SMCAR-LCM-SP, Dover, NJ 07801

Commander, Armament R&D Center, US Army AMCCOM, ATTN: SMCAR-IL, Dover, NJ 07801

Commander, US Army Armament, Munitions and Chemical Command, ATTN:

SMCAR-ESP-L, Rock Island, IL 61299

Commander, US Army Armament, Munitions and Chemical Command, ATTN: SMCAR-SF, Rock Island, IL 61299

Commander, US Army Aviation Research and Development Command, ATTN: AMSAV-E, 4300 Goodfellow Boulevard, St. Louis, MO 63120

Director, Benet Weapons Laboratory, Armament R&D Center, US Army AMCCOM, ATTN: SMCAR-LCB-TL, Watervliet, NY 12189

Director, US Army Air Mobility Research and Development Laboratory, Ames Research Center, Moffett Field, CA 94035

Commander, US Army Communications-Electronics Command, ATTN: AMSEL-ED, Fort Monmouth, NJ 07703

Commander, US Army Electronics Research and Development Command, Technical Support Activity ATTN: DELSD-L, Fort Monmouth, NJ 07703-5301

Commander, US Army Missile Command, ATTN: AMSMI-R, Redstone arsenal, AL 35898 Commander, US Army Missile Command, ATTN: AMSMI-YDL, Redstone Arsenal, AL 35898

Commandant, US Army Missile Munitions Center and School, Redstone Arsenal, AL 35897

SLCBR-TB-E 27 May 1986

SUBJECT: Rack for Temporary Storage of 105 mm HEAT Ammunition

Commander, US Army Tank-Automotive Command, ATTN: AMSTA-TSL, Warren, MI 48090 Director, US Army TRADOC Systems Analysis Activity, ATTN: ATAA-SL, White Sands Missile Range, NM 88002

Project Manager, Ammunition Logistics, ATTN: COL P. Greenberg, Mr. G. Goble, Dover, NJ 07801

Commandant, US Army Infantry School, ATTN: ATSH-CD-CSO-OR, Fort Benning, GA 31905

Commander, US Army Defense Ammo Center & School, ATTN: John Byrd, Savanna, IL 61074

Commander, US Army Development and Employment Agency, ATTN: MODE-TED-SAB, Fort Lewis, WA 98433

HQ, 8th US Army, ATTN: DJ-AM-SS (McDowell), APO San Francisco 96301

Commander, US Army Europe, ATTN: Chief of Staff, APO New York, NY 09403

Commander, US Army Europe, ATTN: AEAGA-SE, APO New York, NY 09403

Commander, US Army Europe, ATTN: G-4, APO New York, NY 09403

Commander, Naval Sea Systems Command, ATTN: SEA 64E (Mr. R. Beauregard), Washington, DC 20362

Commander, Naval Explosive Ordnance Disposal Facility, ATTN: Code 604 (Technical Library), Indian Head, MD 20640

Commander, Naval Surface Weapons Center, ATTN: R15 (J. Ward), Silver Spring, MD 20910

Commander, Fleet Marine Force, Atlantic, ATTN: G-4 (NSAP), Norfolk, VA 23511 Air Force Armament Laboratory, ATTN: AFATL/DLODL, Eglin AFB, FL 32542-5000 AFWL/SUL, Kirtland AFB, NM 87117

Director, US Army Material Systems Analysis Activity, ATTN: AMXSY-D, AMXSY-MP, H. Cohen, AMXSY-R, R. Simmons, Aberdeen Proving Ground, MD 21005-5071

Commander, US Army Test and Evaluation Command, ATTN: AMSTE-TO-F, Aberdeen Proving Ground, MD 21005-5055

Director, US Army Human Engineering Laboratory, ATTN: Jack Waugh, Aberdeen Proving Ground, MD 21005-5001

Commander, Chemical Research and Development Command, AMCCOM, ATTN:

SMCCR-RSP-A, SMCCR-MU, SMCCR-SPS-IL, Aberdeen Proving Ground, MD 21010-5423

INCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER 2. GOVT ACCESSION NO.		
SPECIAL PUBLICATION BRL-SP-46		
4. TITLE (and Subtitle)	5. TYPE OF REPORT & PERIOD COVERED	
4. ITTLE (and Shorter)		
RACK FOR TEMPORARY STORAGE OF 105 MM HEAT		
AMMUNITION	6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(a)	8. CONTRACT OR GRANT NUMBER(s)	
PHILIP M. HOWE		
A DEPTARAGE OF CAMPATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
9. PERFORMING ORGANIZATION NAME AND ADDRESS US Army Ballistic Research Laboratory	AREA & WORK UNIT NUMBERS	
ATTN: AMXBR-TBD	1L162618AH80	
Aberdeen Proving Ground, MD 21005-5066	12102010/4100	
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE	
US Army Ballistic Research Laboratory	March 1985	
ATTN: AMXBR-OD-ST	13. NUMBER OF PAGES	
Aberdeen Proving Ground, MD 21005-5066 14. MONITORING AGENCY NAME & ADDRESS(It different from Controlling Office)	11	
14. MONITORING AGENCY NAME & ADDRESS(If different from Controlling Office)	15. SECURITY CLASS. (of this report)	
	UNCLASSIFIED	
	15. DECLASSIFICATION/OOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report)		
16. DISTRIBUTION STATEMENT (OF MAR REPORT)		
Approved for public release; distribution is unlimited.		
17. DISTRIBUTION STATEMENT (of the abetract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse elde if necessary and identify by block number)		
ammunition storage		
explosives safety distance		
105 mm ammunition		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number	r)	
This special publication describes the construction and use of a rack for the		
temporary storage of 105 mm tank ammunition in densely populated areas, con-		
sistent with explosive safety criteria. The rack, when properly fabricated and		
I have to do a moducos the blast distance for innabited bullutings and the		
In forement distance to 50 feet. Approval for Sitting must be obtained,		
1 . 1 1 Commate DOD Explactives Safety Roard. IL 15 Illended chac		
through channels, from the bod Explosives safety bodies. It is document be used for construction guidance and as part of the documentation		
required for site approval.		

I. INTRODUCTION

The purpose of this report is to outline requirements for construction of a rack which can be used for temporary storage of M456 heat ammunition and other 105 mm tank ammunition in congested areas, consistent with DOD explosives safety criteria.

II. BACKGROUND

Reference is made to DOD 6055.9STD, DOD Ammunition and Explosives Safety Standards and AR 385-64, Ammunition and Explosive Safety Standards, which implements the Department of Defense Standards. Reference is also made to Ballistic Research Laboratory Memorandum Report entitled "Temporary Tank Ammunition Storage Facility" (in press).

Quantity-distance (Q-D) criteria for storage of conventional ammunition are designed to provide an appropriate level of protection against blast and fragment hazards. Explosives safety distance tables prescribe necessary separations and specify maximum quantities of the various classes of explosives permitted in any one location. These tables reflect acceptable minimum criteria for storage and handling of explosives. Such criteria provide reasonable safety within specified limits compatible with the risks of accidental explosion. Both the DOD 6055.9STD and the AR which implements this standard for Army installations and activities provide the opportunity for reduced hazard distances corresponding to reduced fragment and blast hazards, if it can indeed be demonstrated that the hazards are reduced. The burden of proof is upon the initiating activity to demonstrate an acceptable level of safety, however.

III. RATIONALE

The design of this storage rack was predicated upon the assumption that the rack should control explosion size, thus limiting the maximum credible event to some small fraction of the total stores, and should also contol fragment hazards. The rack specified herein limits the maximum credible event to explosion or detonation of one warhead, with a corresponding blast radius (inhabited building distance) of 50 feet. With a 6 inch sand cover (as provided by one layer of sandbags), on the sides and roof, and with front and rear barricades, primary fragments are contained completely, kickouts are reduced to a minimum, and the fragment hazard radius, based upon one hazardous fragment per 600 square feet, is also less than 50 feet. Thus, when 105 mm M456 HEAT ammunition and other nonexplosive conventional antitank ammunition are stored, in their fiber shipping tubes, in the rack, warheads facing to the rear of the rack, the appropriate hazard distance is 50 feet, regardless of the total number of rounds stored at one site.

¹ DOD 6055.9STD, DOD Ammunition and Explosives Safety Standards, July 1984.

 $^{^2}$ AR 385-64, Ammunition and Explosive Safety Standards.

³Philip M. Howe and David L. Collis, "Temporary Tank Ammunition Storage Facility," BRL-MR-3424 (in press).

IV. RACK DESCRIPTION

A shop drawing of the rack is shown in Figure 1. The rack consists of a steel frame made of angle iron, welded or bolted together, and steel spacer rods welded or bolted in position to hold the fiber tubes. The depth of the rack should be at least 45 inches deep, so that the complete round is contained within the rack. Spacing between tiers (vertical) must be at least 10 inches. Steel spacers must be positioned as in Figure 1, with separations of 6 inches, center to center, alternating with spacings of 3 inches, center to center. The support rods on 3 inch centers locate the shipping tubes with respect to each other. On the top of the rack, angle iron or rebar roof supports may be welded in place, as in Figure 1. A sheet of corrugated steel or fiberglass can be used as a rain cover and as a support for the sand cover. A sand cover of one sand bag thickness or 6 inches of loose sand is adequate for fragment protection. Note that cinder blocks, bricks, and concrete blocks are not acceptable for this application, as they serve as a source of secondary hazardous fragments. Sides of the structure are to be barricaded with a minimum of 6 inches of sand (one sandbag thickness), with the barrier joining the roof in such a way that continuous fragment protection is provided. If a natural barricade such as a berm or bank is not located behind the rack, then a sand barrier at least 3 feet thick will be placed behind the rack. The barricade may be placed in contact with the rack or it may be placed an arbitrary distance from the rack. If access to the rear of the rack is desired, a walkway space of at least 32 inches between the rack and rear barrier should be provided. In front of the rack, a barricade of sandbags (6 inches thick), cinder blocks, railroad ties, or other materials must be erected to provide protection from kickouts. The distance of this barricade from the front of the rack may be chosen for operational convenience. The minimum height of both the front and rear barricades must be equal to the top of the rack. An additional foot of height is required for both front and rear barricades for each yard of separation. Breadth of the rack is unlimited. The topmost tier of rounds shall not be more than 79 inches center of the round to ground to insure standing functional reach. This results in a round to round surface separation of 3 inches, which is sufficient to prevent round to round propagation of detonation. Significant deviations in design require approval by the DOD Explosives Safety Board. The rack, with sand covers and side barriers in place, is shown in Figure 2a. Several collocated racks are shown in Figure 2b. Note that the hazard radii are still 50 feet for the larger configuration.

V. USE OF THE RACK

The rack may be used to provide temporary storage of 105 mm tank ammunition, provided the rack is configured as described above, the ammunition is stored in the original shipping tubes, and the tubes are placed in the racks such that the warheads face towards the rear of the rack, provided the rack is located in excess of 50 feet from the nearest inhabited building, and provided express approval for siting is obtained from the DOD Explosives Safety Board.

ACKNOWLEDGEMENTS

This work was sponsored by the DOD Explosives Safety Board. The final rack design was engineered by members of the US Army Human Engineering Laboratory's HELFAST Team, led by Mr. John D. Waugh. The shop drawing was prepared by members of the Engineering Design Division, USAHEL.




Figure 1. Rack




Figure 2. (a) Rack with Sand Covers and Side Barriers in Place.
(b) Several Collocated Racks.

DISTRIBUTION LIST

No. of No. of Copies Copies Organization Organization 12 Administrator 2 Assistant Secretary of Army (I&L) Defense Technical Info Center Department of the Army ATTN: Lewis D. Walker ATTN: DTIC-DDA Cameron Station John Nash Alexandria. VA 22314 Room 3E606, Pentagon Washington, DC 20310 1 HQDA DAMA-ART-M 1 Commander Washington, DC 20310 USA Safety Center ATTN: PESC-Z 5 Chairman Fort Rucker, AL 36360 DOD Explosives Safety Board ATTN: Dr. T. Zaker 1 Commander COL O. Westry US Army Materiel Command Room 856-C ATTN: AMCDRA-ST Hoffman Bldg 1 5001 Eisenhower Avenue 2461 Eisenhower Avenue Alexandria, VA 22333-0001 Alexandria, VA 22331 1 Commander 1 Under Secretary of Defense for US Army Materiel Command Research & Engineering ATTN: AMCSF Department of Defense 5001 Eisenhower Avenue Washington, DC 20301 Alexandria, VA 22333 1 Assistant Secretary of Defense (MRA+L) 1 Director ATTN: EO&SP AMC Field Safety Activity Washington, DC 20301 Charlestown, IN 47111 1 Chief of Research, Development, & 1 HQDA (DAPE-HRS) Acquisition Washington, DC 20310 Department of the Army ATTN: DAMA-CMS-CA, Mr. Lippi 1 Commander Washington, DC 20310 Armament R&D Center US Army AMCCOM 1 HQDA (DAMO-NC) ATTN: SMCAR-TDC Dover. NJ 07801 ATTN: COL R. D. Orton Washington, DC 20310 1 Commander 1 HQDA (DCSLOG) Armament R&D Center US Army AMCCOM ATTN: Elliot Seard Room 1D563, Pentagon ATTN: SMCAR-TSS Dover, NJ 07801 Washington, DC 20310

1 Commander

Armament R&D Center US Army AMCCOM ATTN: SMCAR-LCM-SP Dover, NJ 07801

DISTRIBUTION LIST

No. of Copies Organization

- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-IL
 Dover, NJ 07801
- 1 Commander US Army Armament, Munitions and Chemical Command ATTN: SMCAR-ESP-L Rock Island, IL 61299
- 1 Commander US Army Armament, Munitions and Chemical Command ATTN: SMCAR-SF Rock Island, IL 61299
- 1 Commander
 US Army Aviation Research
 and Development Command
 ATTN: AMSAV-E
 4300 Goodfellow Boulevard
 St. Louis, MO 63120
- 1 Director
 Benet Weapons Laboratory
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-LCB-TL
 Watervliet, NY 12189
- 1 Director US Army Air Mobility Resarch and Development Laboratory Ames Research Center Moffett Field, CA 94035
- 1 Commander
 US Army CommunicationsElectronics Command
 ATTN: AMSEL-ED
 Fort Monmouth, NJ 07703

No. of Copies Organization

- 1 Commander US Army Electronics Research and Development Command Technical Support Activity ATTN: DELSD-L Fort Monmouth, NJ 07703-5301
- 1 Commander
 US Army Missile Command
 ATTN: AMSMI-R
 Redstone arsenal, AL 35898
- 1 Commander
 US Army Missile Command
 ATTN: AMSMI-YDL
 Redstone arsenal, AL 35898
- 1 Commandant
 US Army Missile Munitions Center &
 School
 Redstone Arsenal, AL 35897
- 1 Commander US Army Tank Automotive Command ATTN: AMSTA-TSL Warren, MI 48090
- 1 Director
 US Army TRADOC Systems
 Analysis Activity
 ATTN: ATAA-SL
 White Sands Missile Range,
 NM 88002
- 2 Project Manager
 Ammunition Logistics
 ATTN: COL P. Greenberg
 Mr. G. Goble
 Dover, NJ 07801
- 1 Commandant
 US Army Infantry School
 ATTN: ATSH-CD-CSO-OR
 Fort Benning, GA 31905

DISTRIBUTION LIST

No. of Copies Organization

No. of Copies Organization

- 1 Commander US Army Defense Ammo Center & School ATTN: John Byrd Savanna, IL 61074
- 1 Commander
 US Army Development & Employment
 Agency
 ATTN: MODE-TED-SAB
 Fort Lewis, WA 98433
- 1 HQ, 8th US Army ATTN: DJ-AM-SS (McDowell) APO San Francisco 96301
- 1 Commander US Army Europe ATTN: Chief of Staff APO New York, NY 09403
- 1 Commander US Army Europe ATTN: AEAGA-SE APO New York, NY 09403
- 1 Commander US Army Europe ATTN: G-4 APO New York, NY 09403
- 1 Commander
 Naval Explosive Ordnance
 Disposal Facility
 ATTN: Technical Library,
 Code 604
 Indian Head, MD 20640
- 1 Commander Naval Surface Weapons Center ATTN: J. Ward, R15 Silver Spring, MD 20910

1 Commander
Fleet Marine Force, Atlantic
ATTN: G-4 (NSAP)
Norfolk, VA 23511

- 1 Air Force Armament Laboratory ATTN: AFATL/DLODL Eglin AFB, FL 32542-5000
- 1 AFWL/SUL Kirtland AFB, NM 87117

Aberdeen Proving Ground

Dir, USAMSAA
ATTN: AMXSY-D
AMXSY-MP, H. Cohen
AMXSY-R, R. Simmons
Cdr, USATECOM
ATTN: AMSTE-TO-F
Cdr, USAHEL
ATTN: Jack Waugh
Cdr, CRDC, AMCCOM

ATTN: SMCCR-RSP-A SMCCR-MU SMCCR-SPS-IL

USER EVALUATION SHEET/CHANGE OF ADDRESS

This Laboratory undertakes a continuing effort to improve the quality of the reports it publishes. Your comments/answers to the items/questions below will aid us in our efforts.

1. BRL Re	port Number	Date of Report
2. Date R	eport Received	
3. Does to other area	his report satisfy a need? (Coof interest for which the rep	omment on purpose, related project, or ort will be used.)
		g used? (Information source, design
as man-hou		ed to any quantitative savings as far costs avoided or efficiencies achieved,
		should be changed to improve future ion, technical content, format, etc.)
	Name	
CURRENT ADDRESS	Organization	
	Address	
	City, State, Zip	
7. If indi New or Corr	cating a Change of Address or ect Address in Block 6 above a	Address Correction, please provide the nd the Old or Incorrect address below.
	Name	
OLD ADDRESS	Organization	
	Address	
	City, State, Zip	

(Remove this sheet along the perforation, fold as indicated, staple or tape closed, and mail.)